



NOTE

BUTTERFLY VALVE ACTUATORS TO BE ON THE LEFT SIDE, WHEN VIEWED FROM THE FITTING THROUGH THE VALVE, AS SHOWN ABOVE

Revised: April 22, 2020

RECOMMENDED BY:	REV.	DATE	BY
Engineering			
APPROVED BY:			
Operations			

**PHELAN PIÑON HILLS
 COMMUNITY SERVICES DISTRICT**
**BUTTERFLY VALVE ACTUATORS
 LOCATION AND INSTALLATION**



STD. DWG. No.

W-8